GIBRALTAR PORT AUTHORITY
Tel: +350 200 46254
Fax: +350 200 77011
Email: gpaenquiries@port.gov.gi
Web: www.gibraltarport.com

09th July 2026

LOCAL NOTICE TO MARINERS 2026 LNTM 030(A) - DEFECTIVE NAVIGATIONAL CARDINAL MARKER (SOUTH) AT SANDY BAY - (UPDATE!!!!)

Mariners, Owners, Agents and Charterers are advised to navigate with caution as the southernmost cardinal marker light at Sandy Bay is currently not working due to suspected vandalism to the actual light using spray paint and has been broken causing severe water ingress.

Please see below diagram:



The GPA is conducting an investigation as a result of this suspected vandalism.
The GPA reminds the public that these lights are paramount in the safe navigation through BGTW and encourage members of the public to come forward with any information regarding the damages.

Deputy VTS Manager
Gibraltar Port Authority

Owners, Agents and Charterers should ensure that the contents of Local Notice to Mariners are made known to Masters and persons in charge of their vessels.
All notices are available to view on the Gibraltar Port Authority website at: www.gibraltarport.com